FUSS & O'NEILL
Manufacturing Solutions, LLC
"Enhancing Productivity"

X	Basic Skill
X	Counter Measure
X	Accessibility
X	Safety
O	Mistake Proofing
X	Productivity

Regulated PM's

Attachment B
QUARTERLY INSPECTION OF
CHROMIC ACID ANODIZING FUME SCRUBBER

DATE	1 LEAKS IN THE DUCTWORK LEADING FROM ANODIZING TANK (YES/NO)	2 CHEMICAL ATTACK ON STRUCTURAL INTEGRITY (YES/NO)	3 BUILDUP ON PADS (YES/NO)	4 BREAKTHROUGH OF CHROMIC ACID THROUGH MESH PAD CLOSEST TO FAN[1] (YES/NO)	5 SPRAY NOZZLES WORKING CORRECTLY[2] (YES/NO)	6 PROPER DRAINAGE (YES/NO)	7 INSPECTOR'S SIGNATURE

Do you have Regulated PM's that have to be completed, such as a Fume Scrubber, or other environmental equipment? If you can match the PM to the paperwork that has to be signed off, you can cut out much of the waste.

This PM became very visual and each number matched a number on the PM sign off sheet. As the PM was completed the maintenance person, checked off and signed. This PM went from two people 8 hours, to one person 2 hours, and the PM paperwork exactly matched the regulated PM sign off sheet.



John Kravontka | 146 Hartford Road – Manchester, CT 06040 | (800) 286-2469 x5399 | JKravontka@FandO.com