



FUSS & O'NEILL
 Manufacturing Solutions, LLC
 "Enhancing Productivity"



Specialty
 MINERALS

X	Basic Skill
X	Counter Measure
O	Accessibility
O	Safety
O	Mistake Proofing
O	Productivity

Magnetic wall

One way to display information in your plant is to put it up on a wall. If the wall could support magnetic placards, that would make it easy to display. Try painting the wall with magnetic paint.



It is very expensive, about \$90/gallon, but in the right situation, could work well for you.

Paint wall with magnetic paint to make it easy to display your metrics.