



FUSS & O'NEILL
Manufacturing Solutions, LLC
"Enhancing Productivity"

X	Basic Skill
X	Counter Measure
X	Accessibility
O	Safety
X	Mistake Proofing
X	Productivity

Storage: Organized Min / Max on Critical Spare Parts

When a machine bearing has deteriorated, normally from contamination or improper lubrication, you hope that there are replacement bearings in stock...



As illustrated, there are bearings in stock! Each drawer and bearing type is labeled. This makes it easy to verify that a sufficient amount are available, then re-order per the Min/Max.