


Single Point Lesson #169

Using a mirror to locate blind holes.

Sometimes reassembling machine components can take 5X to 10X longer than the time it took to disassemble them...

X	Basic Skill
O	Counter Measure
X	Accessibility
O	Safety
O	Mistake Proofing
X	Productivity



In the picture above, notice the red oval illustrates via the mirror being used to understand why the cap bolt won't go back into its hole! Somehow, the wrong component was mounted, and it's clearly visible.