



Single Point Lesson #195

Shielding Lubrication Lines

X	Basic Skill
X	Counter Measure
O	Accessibility
X	Safety
X	Mistake Proofing
X	Productivity

Hand tools and die sets easily kink or gouge copper lines...



One inexpensive method to keep the copper in good shape is to add a outer shield to it !



We enjoy hearing from our subscribers. If you have ideas that you feel will help our readers as Single Point Lessons, please send us your lessons. Several subscribers have already submitted lessons that have been included in our previous mailings. Please send your ideas to: jkravontka@fando.com

