



FUSS & O'NEILL
 Manufacturing Solutions, LLC
"Enhancing Productivity"

X	Basic Skill
X	Counter Measure
X	Accessibility
X	Safety
O	Mistake Proofing
X	Productivity

Wiring 5'S Observations



Many times our equipment wiring is in disorganization. It is very difficult to clean around the wiring, and it can be a very unsafe condition, from a tripping hazard point of view.



Be observant!!

Look for wiring that is disorganized. Look for equipment that is very difficult to clean around.

When walking the manufacturing floor, look at the lower levels of the equipment, where wiring can droop and hang.

Open up a maintenance work order to 5'S, organize, wire tie, relocate and/or re-route the wiring.