





FUSS & O'NEILL
 Manufacturing Solutions, LLC
"Enhancing Productivity"

X	Basic Skill
X	Counter Measure
X	Accessibility
X	Safety
X	Mistake Proofing
X	Productivity

Are your Gauges tough to see, then Re-plumb them !



When this machine is turned on, can you tell what PSI the Gauge is at?



Much Easier to see now, after extending it higher. Then label with gage marking material.

For less than \$10, re-plumb Gauges to use them!