




**FUSS & O'NEILL**  
Manufacturing Solutions, LLC  
*"Enhancing Productivity"*

X	Basic Skill
O	Counter Measure
O	Accessibility
X	Safety
X	Mistake Proofing
X	Productivity

### Non-contact temperature probe info...

**As companies implement pro-active maintenance methods using non-contact temperature probes, please be aware that they can be inaccurate at distances & on certain surfaces. Notice the visual on each type of probe utilized...**



**We utilize many types of probes, and typically find that at 3 – 5 feet away from a component, the \$50 - \$80 probes are 5 – 10 degrees lower than the actual temperature. This was compared with a \$450 probe.**