




**FUSS & O'NEILL**  
 Manufacturing Solutions, LLC  
*"Enhancing Productivity"*

X	Basic Skill
X	Counter Measure
X	Accessibility
X	Safety
O	Mistake Proofing
X	Productivity

## Heads-Up: Run Away Drive

Sometimes the freak accidents do happen... Notice how far the drive gear is off of the shaft. It is only a matter of time (minutes / hours in this case) when this occurs.



Performing routine inspections of drive systems will find issues quickly. Installing Lexan "viewing ports" make it easy to check – even with machine functioning