






FUSS & O'NEILL
 Manufacturing Solutions, LLC
 "Enhancing Productivity"

X	Basic Skill
X	CounterMeasure
X	Accessibility
X	Safety
X	Mistake Proofing
X	Productivity

Grease Fitting Location



Look for grease fittings that are impossible to apply grease to. How are they currently being greased?



Where we find those fittings, let's relocate them, rotate the bearings, install 90 degree fittings, etc. Then diagram the location of all of the fittings, with numbers, type of grease, amount, time frame, etc.

